

MUGEN COATING PREMIUM High Efficiency Lens Form 3-Flute End Mill

MLFH330



Realizes large pick feed even with small size diameter Specialized lens form 3-Flute end mill improves productivity compared to ball end mills

MUGEN COATING PREMIUM High Efficiency Lens Form 3-Flute End Mill





2-2

Large enough chip pockets prevent unexpected chipping of cutting edge or chip jamming due to the size of the chips by large pick feed.



Comparison of machining efficiency with conventional products

Work material : STAVAX (52HRC) Coolant : Oil mist Machining size : 14.5 × 30.8 × 3 mm

Achieves high efficiency with both productivity and cost performance through shortening machining time and increasing tool life.

Process	Conventional 2-flute ball end mill	MLFH330
Tool size	R0.5 × 3	φ1×R1 × 3
Spindle speed [min ⁻¹]	40,000	27,500
Feed [mm/min]	2,500	3,750
Depth of cut ap × ae [mm]	0.1 × 0.3	0.1 × 0.425
Feed per tooth [mm/tooth]	0.031	0.045
Machining time (1 pocket)	25 min	15 min

Machining time reduced by 40%

Comparison between machined pocket quantity and flank wear width



Quantity of machined pockets (pocket)

Realizes large pick feed even with small size diameter Specialized lens form 3-Flute end mill improves productivity compared to ball end mills

If your CAM can use lens form end mills, please use it as is. * Make an inquiry to CAM manufacturer regarding the availability of tool registration and tool path generation. Example of procedure when the shape of this tool cannot be defined with the CAM are using. \Rightarrow There are no special settings other than tool settings. For open shape Machining example 1 Key points of this machining shape 1. No walls 2. Maximum inclined angle Setting for Roughing process (Same for Finishing) Tool setting Tool : MLFH330 φ6×R8×20 Shape Define the tool shape as "Ball end mill" Shape Ball Outer diameter (D) 16 Enter twice the end tooth bottom radius (R) of Ball radius (R) 8 MLFH330 as the tool diameter. Flute number 3 Taper angle 0 Length of cut 6 Model shape adjustment Adjust and extend the surface of the model shape so that the tool tip overruns more than 50% diameter of the tool diameter entered above parameter. ※ Recommended feed direction is the same as the feed rate is stable on the machined surface. Make sure to set the inclined angle within the maximum inclined Setting for Finishing process angle that does not exceed the machining range of the end tooth bottom radius. Maximum inclined angle means the workpiece that can be machined without problems with the machining allowance shown in the recommended cutting conditions. Exceed the maximum inclined angle Within the maximum inclined angle If the maximum inclined angle Stock is exceeded, machined surface allowance quality would be deteriorated Corner radius Stock Corner radius allowance End tooth bottom radius End tooth bottom radius Inclined angle Inclined

angle



Tool setting

Shape	For example Tool · MI FH330 φ6×R8×20
Shape Corner radius	Define the tool shape as "Corner radius end mill"
Outer diameter (D)Corner radius (R)0.789Flute number3Taper angle0Length of cut	Enter the theoretical corner radius(R) of MLFH330 shown below.

Leftover materials

When defined as a corner radius end mill, the leftover materials between the actual cutting edge and the theoretical cutting edge will be generated, especially in the corners. Refer to the table below for the amount of leftover materials.



Image of the leftover materials when defined as corner radius end mill with theoretical corner R.







MUGEN COATING PREMIUM High Efficiency Lens Form 3-Flute End Mill

Total 7 Sizes

Realizes large pick feed even with small size diameter Specialized lens form 3-Flute end mill improves productivity compared to ball end mills



	¢d () −0. 001 −0. 003
R accuracy on corner radius is ±0.01mm	3D
$\begin{array}{c} & & & \\ & & & \\ & & & \\ & & & \\ & & & \\ &$	¢ d -0.003

- Adopt MUGEN COATING PREMUIM for hardened steel to support machining hardened steel up to 65HRC.
- 3-flute lens form combines larger pick feed than ball end mills improve machining efficiency.
- High productivity can be achieved by using the 5-axis machining to take large pick feeds while keeping the cut point constant.

Work Material		
Prehardened Steel P	Harden	ed Steel 占
	40~60HRC	\sim 65HR
		\cap

		U U	0	-				U	nit [Size : mm]
Code No.	Dia. (D)	End Tooth Bottom Radius (R)	Under Neck Length (貨)	Corner Radius (r)	Length of Cut (≀)	Neck Dia. (d2)	Neck Taper Angle (γ)	Shank Dia. (d)	Overall Length (L)
08-00790-10103	1	R1	3	R0.03	1	0.95	12°	6	50
08-00790-20206	2	R2	6	R0.05	2	1.91	12°	6	50
08-00790-30309	3	R3	9	R0.1	3	2.85	12°	6	60
08-00790-40412	4	R4	12	R0.1	4	3.8	12°	6	60
08-00790-50515	5	R5	15	R0.2	5	4.75	12°	6	60
08-00790-60620	6	R6	20	R0.3	6	5.7	-	6	60
08-00790-60820	6	R8	20	R0.3	6	5.7	-	6	60

How to Order When you order, indicate MLFH330 (D)×(R)×(ℓ 1).

(y) is reference value.

Machining case



Process	Finishing
Tool	MLFH330 φ6 × R8 × 20
Spindle speed [min-1]	9,650
Feed [mm/min]	2,100
Stock allowance [mm]	0.04
Pick feed [mm]	0.08
Inclined angle [°]	$2\sim 26$

%5-axis machining allows machining exceeding the maximum inclined angle.

Work material : STAVAX (52HRC) Work size : 200 × 100 × 30 mm Curvature of shape : R500 × R250 Machining depth: 16 mm Coolant ; Oil mist







Straight and uniform machined surface quality

	Unit [µm]
Surface r	oughness
Ra	0.12

Recommended Conditions

Roughing

Work Material Prehadened Steels Hardened Steels HPM·NAK(~42HRC) HAP38·STAVAX·SKD61(~55HRC)			Hardened Steels SKD11·PD613(~62HRC)				High Speed Steels SKH(~65HRC)								
Dia	End Tooth	End Tooth	End Tooth Under	Depth of Cut		Feed Spindle Speed		Depth	of Cut	Feed	Spindle Speed	Depth of Cut		Feed	Spindle Speed
	Radius	Length	a _{p mm}	a _{e mm}	mm/min	min ⁻¹	a _{p mm}	a _{e mm}	mm/min	min ⁻¹	a _{p mm}	a _{e mm}	mm/min	min ⁻¹	
1	1	3	0.1	0.4	3,500	26,000	0.1	0.28	2,400	21,000	0.08	0.15	1,500	14,000	
2	2	6	0.2	0.7	3,500	16,000	0.2	0.5	2,400	12,000	0.15	0.45	1,800	10,000	
3	3	9	0.2	1.1	4,200	13,000	0.2	0.85	3,000	10,000	0.2	0.7	2,200	7,600	
4	4	12	0.3	2.1	4,200	11,000	0.2	1.2	3,000	9,000	0.2	1	2,200	6,600	
5	5	15	0.3	2.4	4,200	10,000	0.2	1.6	3,000	8,200	0.2	1.2	2,200	6,000	
6	6	20	0.3	2.8	4,200	9,500	0.3	1.8	3,000	7,000	0.2	1.6	2,200	5,600	
6	8	20	0.3	3.2	4,200	9,000	0.3	2	3,000	6,500	0.2	1.8	2,200	5,000	
	Notes		 %1 Dej %2 Adj %3 In c %4 Req %5 If m %6 Atte %7 Adj %8 Ove %9 Oil %10 W %11 W 	0.3 3.2 4,200 9,000 0.3 2 3,000 6,500 0.2 1.8 2,200 5,000 **1 Depth of Cut: ap=Axial Depth of Cut / ae=Radial Depth of Cut. **2 Adjust milling condition according to machine rigidity and clamp condition of work material. **3 In case of chattering etc., please adjust cutting conditions if necessary. **4 Required careful set up of milling conditions, tool path and etc. at cutting parts, such as corners where will become overloaded. *5 If machine tool vibration is high during machining, adjust the feed rate as necessary. **6 Attention to a risk of chipping and breakage when insucient chip flow. *7 Adjust both spindle speed and feed at the same rate. **8 Overhang of end mill should be as short as possible form spindle nose. *9 Oil mist coolant is recommended. **10 When creating toolpaths in CAM software, tool difinition is recommended by using a lens-shaped end mill. *11 **11 When measuring tool lengths, download the DXF of the tool geometry from our website and check the tool geometry before measuring.							easuring.				

Finishing

Work Material						Prehaden Harden HPM∙NAk HAP38∙ SKD61(∕	ed Steels ed Steels (~42HRC) STAVAX• ~55HRC)	Hardene SKD11 (~62	ed Steels •PD613 HRC)	High Spe Sł (~65	ed Steels (H HRC)	
	End	Under	Maximum	Cusp	Depth	of Cut	Feed	Spindle Speed	Feed	Spindle Speed	Feed	Spindle Speed
Dia.	Bottom Radius	Neck Length	Inclined Angle	Height µm	Stock Allowance mm	Pick Feed mm	mm/min	min ⁻¹	mm/min	min ⁻¹	mm/min	min ⁻¹
1	1	3	17°	0.1	0.02	0.025	2,000	26,000	1,700	21,000	1,100	14,000
2	2	6	20°	0.1	0.02	0.04	1,900	16,000	1,400	12,000	1,100	10,000
3	3	9	20°	0.1	0.03	0.05	1,900	13,000	1,400	10,000	1,100	7,600
4	4	12	21°	0.1	0.03	0.055	1,800	11,000	1,400	9,000	1,100	6,600
5	5	15	21°	0.1	0.04	0.06	1,800	10,000	1,400	8,200	1,100	6,000
6	6	20	21°	0.1	0.04	0.065	1,800	9,500	1,400	7,000	1,100	5,600
6	8	20	14°	0.1	0.04	0.08	2,100	9,000	1,500	6,500	1,200	5,000

Notes	 **1 The cutting condition is set that the pick feed achieves a cusp height of 0.1 µm, feed per tooth achieves as same amount as pick feed. Adjust according to machine rigidity and accuracy requirements. **2 Adjust milling condition according to machine rigidity and clamp condition of work material. **3 Overhang of end mill should be as short as possible form spindle nose. **4 Oil mist coolant is recommended. **5 Adjust both spindle speed and feed at the same rate. **6 Cutting depth set with care, as the larger the depth of cut, the smaller the maximum inclination angle. **7 When creating toolpaths in CAM software, tool difinition is recommended by using a lens-shaped end mill. **8 When measuring tool lengths, download the DXF of the tool geometry from our website and check the tool geometry before measuring.
-------	--

NS TOOL CO.,LTD.

www.ns-tool.com 6F., Sumitomo Fudosan Oimachi Ekimae Bldg., 1-28-1 Oi, Shinagawa-ku, Tokyo 140-0014, Japan TEL. +81-3-3774-2459 FAX. +81-3-3774-2460



us.ns-tool.com 2265 Building # 3, Star CT., Rochester Hills, MI 48309, USA TEL. +1-248-829-1960



Attention on Safety

1) When removing tools from cases, be careful of getting-out of tools and don't touch directly the cutting edges.

- 2) Never touch the cutting edges directly with bare hand.
- 3) Use safety covers and eye protection, as tools may be broken.
- 4) Use holders, etc. that match the tools and nature of the processing operations. The tool should be firmly attached to the holder to prevent shaking.
- 5) The work materials clamp firmly.
- 6) Make sure of dimensions of tools and work pieces before starting operation.
- 7) It is necessary to adjust conditions according to the dimensions of work materials and the machine.
- 8) Select a cutting fluid appropriate to the particular usage. Using a non-water cutting fluid could lead to fires due to sparks generated during processing or heat caused by breakage. Ensure that you take proper fire-prevention measures.
- 9) If abnormal sound, etc. occurs during processing, stop the machine immediately.

10) Don't modify tools.



MLFH330_A1_202504_EN